



Jacobs Wells Baths

July – September 2025



Main Hall

Images by Fidel Meraz, Trustee





Main Hall

Asbestech decontamination units in-situ, cleared end Sept for Carrek to come on site and begin main roof works – scaffolding to be erected in pool basin

South Studio

Site offices set up for works and intermediate site uses
South Studio roof repairs and masonry works completing Oct 25






Pump Room



Pump Room

Asbestos decontamination completed
Intermediate works programme to support meanwhile uses under way





North Wing



North Wing

Slate floor tiles lifted
and asbestos
decontamination works
completed



Key Funders & Supporters

